







DS1 - EL  
(Surface Mounted)





PRT - E  
(Flush mounted)



Optional Remote Sensor



Setback Time Switch  
Required to activate  
4°C setback on DS1 - EL



### UPONOR 230V CONTROL CENTRE

Switched Fuse Spur  
3 Amp Fuse

Connect to Switch Live (A)

